



NeXtrac[®] Grip Connector

Parts List:

Grip Connector



Allen Wrench

Required Tools

1. Loosen the side screw from the Grip Connector with the Allen wrench. You will see the inner moveable ridge attached by the screw move closer to the ridge extrusion of the Grip Connector. (Figure A).
2. Once they are close together, it is simple to slide the Grip Connector into the dovetail groove of a Beltrac 3000 post. (Figure B).
3. Then, tighten the screw with the Allen wrench to secure your NeXtrac[®] product to the post. Some NeXtrac[®] products utilize more than one Grip Connector. Make sure all Grip Connectors are connected and tightened for a secure fit (Figure C).

